

Operation and Location	Facility	Type	Status	Tailings Embankment Construction Method
Alma, Quebec, Canada	Aluminerie Saguenay Lac St-Jean (AP40) -SLSJ	Water	Active	
Alumar, Sao Luis, Brazil	RSA1	Tailings	Post closure	Single embankment
Alumar, Sao Luis, Brazil	RSA2	Tailings	Under rehabilitation	Upstream
Alumar, Sao Luis, Brazil	RSA3	Tailings	Under rehabilitation	Upstream
Alumar, Sao Luis, Brazil	RSA4	Tailings	Under rehabilitation	Upstream
Alumar, Sao Luis, Brazil	RSA5	Tailings	Active	Upstream
Alumar, Sao Luis, Brazil	RSA6	Tailings	Active	Single embankment
Alumar, Sao Luis, Brazil	RSA7	Tailings	Active	Single embankment
Argyle, WA, Australia	AK1 and all saddle dams	Tailings	Active	Downstream
Argyle, WA, Australia	ARD Waste Rock Dam (Jacko's Dam) WSF	Water	Active	
Argyle, WA, Australia	Gap Dam WSF	Water	Active	
Bell Bay, TAS, Australia	Howell Reservoir	Water	Active	
Bell Bay, TAS, Australia	Lauriston Reservoir	Water	Active	
Bell Bay, TAS, Australia	Red Mud Dam	Tailings	Inactive	Single embankment
Blackbird, Idaho, USA	7000 Dam	Water	Active	
Blackbird, Idaho, USA	7100 Dam	Water	Active	
Blackbird, Idaho, USA	West Fork TSF	Tailings	Post closure	Upstream
Boron, California, USA	Boric Acid Pond 1	Tailings	Active	Centreline
Boron, California, USA	Boric Acid Pond 2	Tailings	Active	Centreline
Boron, California, USA	Boric Acid Pond 3	Tailings	Active	Centreline
Boron, California, USA	Boric Acid Pond 4	Tailings	Active	Centreline
Boron, California, USA	Boric Acid Pond 5	Tailings	Active	Centreline

Boron, California, USA	Boric Acid Pond 6	Tailings	Active	Single embankment
Boron, California, USA	Boric Acid Pond 7A	Tailings	Active	Single embankment
Boron, California, USA	Boric Acid Pond 7B	Tailings	Active	Single embankment
Boron, California, USA	Evaporation Ponds R1	Tailings	Inactive	Single embankment
Boron, California, USA	Evaporation Ponds R2	Tailings	Inactive	Single embankment
Boron, California, USA	Evaporation Ponds R3	Tailings	Under construction	Single embankment
Boron, California, USA	Evaporation Ponds R4	Tailings	Active	Single embankment
Boron, California, USA	Evaporation Ponds R5	Tailings	Active	Single embankment
Boron, California, USA	Evaporation Ponds R6	Tailings	Active	Single embankment
Boron, California, USA	Evaporation Ponds R7	Tailings	Active	Single embankment
Boron, California, USA	Flood Control Catchment 1	Water	Active	
Boron, California, USA	Flood Control Catchment 2	Water	Active	
Boron, California, USA	Flood Control Catchment 23	Water	Active	
Boron, California, USA	Flood Control Catchment 3	Water	Active	
Boron, California, USA	Flood Control Catchment 4	Water	Active	
Boron, California, USA	Flood Control Catchment 5A and 5B	Water	Active	
Boron, California, USA	Flood Control Catchment 7	Water	Active	
Boron, California, USA	Pond 4	Tailings	Closed	Single embankment
Boron, California, USA	Pond 5	Tailings	Closed	Single embankment
Boron, California, USA	Pond 6	Tailings	Active	Single embankment
Compagnie de Bauxite de la Guinee (CBG), Guinea	Étang central	Water	Active	
Compagnie de Bauxite de la Guinee (CBG), Guinea	Kamsar - Étang Est	Water	Active	
Compagnie de Bauxite de la Guinee (CBG), Guinea	Kamsar - Étang Ouest	Water	Active	
Compagnie de Bauxite de la Guinee (CBG), Guinea	Sangaredi - Ndangara	Water	Active	
Dampier Salt, WA, Australia	Bitterns Crystallisers - Dampier	Water	Active	
Dampier Salt, WA, Australia	Concentration Pond System - Port Hedland	Water	Active	
Dampier Salt, WA, Australia	Concentration Ponds - Dampier	Water	Active	

Dampier Salt, WA, Australia	Crystalliser - Port Hedland	Water	Active	
Dampier Salt, WA, Australia	Crystalliser Field - Lake McLeod	Water	Active	
Dampier Salt, WA, Australia	Crystallisers - Dampier	Water	Active	
Dampier Salt, WA, Australia	Gypsum Bore Dam WSF	Water	Active	
Dampier Salt, WA, Australia	Gypsum Freshwater Dam WSF	Water	Active	
Dampier Salt, WA, Australia	Lake Dam - Lake McLeod WSF	Water	Active	
Dampier Salt, WA, Australia	Pickle Pond 9 - Port Hedland	Water	Active	
Dampier Salt, WA, Australia	Site Bore Dam - Lake McLeod WSF	Water	Active	
Dampier Salt, WA, Australia	Wash Plant Settling Pond - Dampier	Water	Active	
Dampier Salt, WA, Australia	Wash Plant Settling Pond - Lake McLeod	Water	Active	
Dampier Salt, WA, Australia	Washplant Settling Pond - Port Hedland	Water	Active	
Diavik, Northwest Territories, Canada	A154 Dike WSF	Water	Active	
Diavik, Northwest Territories, Canada	A21 Dike WSF	Water	Active	
Diavik, Northwest Territories, Canada	A418 Dike WSF	Water	Active	
Diavik, Northwest Territories, Canada	North Inlet East Dike WSF	Water	Active	
Diavik, Northwest Territories, Canada	Processed Kimberlite Containment (PKC) Facility	Tailings	Active	Downstream
ERA, NT, Australia	Pit 1 TSF	Tailings	Closed	No embankment - excavated storage facility
ERA, NT, Australia	Pit 3 TSF	Tailings	Active	No embankment - excavated storage facility
ERA, NT, Australia	RP1	Water	Active	
ERA, NT, Australia	RP6	Water	Active	
ERA, NT, Australia	TSF	Tailings	Inactive	Downstream
Escondida, Chile	Hamburgo	Tailings	Inactive	Natural depression with perimeter embankment (downstream/single)
Escondida, Chile	Laguna Seca TSF	Tailings	Active	Downstream
FalCon Diamond Exploration Project, Saskatchewan, Canada	Star Souite	Tailings	Active	Centreline
Gardanne, France*	Mange Garri Dyke D5	Tailings	Active	Single embankment
Gardanne, France*	Mange Garri Dyke D6	Tailings	Active	Single embankment

Gardanne, France*	Mange Garri Dyke D7	Tailings	Active	Single embankment
Gove, NT, Australia	Labyrinth and Settling Ponds	Water	Inactive	
Gove, NT, Australia	Northern Ponds	Tailings	Under rehabilitation	Downstream
Gove, NT, Australia	Pond 2	Tailings	Inactive	Downstream
Gove, NT, Australia	Pond 3	Tailings	Closed	Upstream
Gove, NT, Australia	Pond 4	Tailings	Closed	Downstream
Gove, NT, Australia	Pond 5	Tailings	Inactive	Centreline, Downstream
Gove, NT, Australia	Pond 6	Tailings	Active	Centreline, Downstream
Gove, NT, Australia	Pond 6S	Water	Active	
Gove, NT, Australia	Pond 6S Decant	Water	Active	
Gove, NT, Australia	Pond 7	Water	Active	
Gove, NT, Australia	Pond 8	Water	Active	
Holden, Washington, USA	Tailings Piles #1, #2 and #3	Tailings	Closed	Upstream
Holden, Washington, USA	Underground mine water storage and Water Treatment Plant pond	Water	Closed	
Hope Downs 4, WA, Australia	DSP in-pit WFSF	Tailings	Active	No embankment - excavated storage facility
Hope Downs 4, WA, Australia	WFSF Stage 2	Tailings	Active	Downstream
Iron Ore Canada, Newfoundland and Labrador, Canada	Wabush lake disposal	Tailings	Active	Lake discharge
Kelian, Indonesia	Nakan Waste Rock Dam	Water	Post closure	
Kelian, Indonesia	Namuk Tailings Storage Facility	Tailings	Post closure	Upstream
Kennecott Utah Copper, Utah, USA	South (Magna) TSF Impoundment	Tailings	Inactive	Upstream
Kennecott Utah Copper, Utah, USA	Barneys Canyon Mine - Storm Water Ponds WSF	Water	Under construction	
Kennecott Utah Copper, Utah, USA	Copperton Reservoirs	Water	Active	
Kennecott Utah Copper, Utah, USA	Kessler Canyon Dam No. 10 WSF	Water	Active	
Kennecott Utah Copper, Utah, USA	Kessler Canyon Dam No. 11 WSF	Water	Active	
Kennecott Utah Copper, Utah, USA	Kessler Canyon Dam No. 6 WSF	Water	Active	
Kennecott Utah Copper, Utah, USA	Large Bingham Reservoir WSF	Water	Active	
Kennecott Utah Copper, Utah, USA	Magna Reservoir WSF	Water	Active	
Kennecott Utah Copper, Utah, USA	North TSF Impoundment	Tailings	Active	Centreline

Kennecott Utah Copper, Utah, USA	Oquirrh Lake WSF	Water	Active	
Kennecott Utah Copper, Utah, USA	Small Bingham Reservoir WSF	Water	Active	
Kennecott Utah Copper, Utah, USA	Smelter East Ponds	Water	Active	
Kennecott Utah Copper, Utah, USA	Smelter West Ponds	Water	Active	
Kitimat & Kemano, British Columbia, Canada	Bear Lake Dams #1, 2, 3	Water	Active	
Kitimat & Kemano, British Columbia, Canada	Cheslatta Lake, Dyke	Water	Active	
Kitimat & Kemano, British Columbia, Canada	Cut-off Creek Dam #1, 2, 3	Water	Active	
Kitimat & Kemano, British Columbia, Canada	Nechako Reservoir Kenney dam	Water	Active	
Kitimat & Kemano, British Columbia, Canada	Nechako Reservoir Skins Lake spillway	Water	Active	
Marandoo, WA, Australia	HAP - Dam	Water	Active	
Marandoo, WA, Australia	Southern WFSF	Tailings	Under construction	Downstream
Marandoo, WA, Australia	WFSF	Tailings	Active	Downstream
McGill, Nevada, USA	Kennecott Nevada Copper	Tailings	Closed	Upstream
Mineracao Rio do Norte (MRN), Brazil	L2	Water	Active	
Mineracao Rio do Norte (MRN), Brazil	Pater Lake	Water	Active	
Mineracao Rio do Norte (MRN), Brazil	SP-1	Tailings	Closed	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-10	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-11	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-12	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-13	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-14	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-15	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-16	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-2/3N	Tailings	Closed	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-2/3S	Tailings	Closed	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-4L	Tailings	Closed	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-4N	Tailings	Active	Upstream

Mineracao Rio do Norte (MRN), Brazil	SP-4S	Tailings	Active	Upstream
Mineracao Rio do Norte (MRN), Brazil	SP-5L	Tailings	Active	Upstream
Mineracao Rio do Norte (MRN), Brazil	SP-50	Tailings	Active	Upstream
Mineracao Rio do Norte (MRN), Brazil	SP-6	Tailings	Active	Upstream
Mineracao Rio do Norte (MRN), Brazil	SP-7A	Tailings	Active	Upstream
Mineracao Rio do Norte (MRN), Brazil	SP-7B	Tailings	Active	Upstream
Mineracao Rio do Norte (MRN), Brazil	SP-7C	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-8	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-9	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	SP-9A	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	TP1	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	TP2	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	TP3	Tailings	Active	Single embankment
Mineracao Rio do Norte (MRN), Brazil	Urbano Lake	Water	Active	
Montgrand, Marseille, France	Montgrand 0128	Tailings	Post closure	Single embankment
Mt Rosser, Jamaica	Mt Rosser Tailings dam	Tailings	Inactive	Centreline
Nammuldi, WA, Australia	NBWT WFSF	Tailings	Active	Downstream
Olette, French Pyrénées, France	Olette 0425	Tailings	Post closure	Upstream
Oyu Tolgoi, Mongolia	Process water ponds	Water	Active	
Oyu Tolgoi, Mongolia	Raw Water Lagoons	Water	Active	
Oyu Tolgoi, Mongolia	TC1	Tailings	Active	Downstream
Paraburdoo, WA, Australia	TSF1	Tailings	Active	Upstream
QC Power - Chute-à-Caron, Quebec, Canada	Barrage de Chute-à-Caron	Water	Active	
QC Power - Chute-à-la-Savane, Quebec, Canada	Barrage de la Chute-à-la Savane	Water	Active	
QC Power - Chute-du-Diable, Quebec, Canada	Barrage de la Chute-du-Diable	Water	Active	
QC Power - Chute-du-Diable, Quebec, Canada	Digue de la Chute-du-Diable	Water	Active	
QC Power - Isle-Maligne	Barrage de l'Isle-Maligne	Water	Active	
QC Power - Isle-Maligne	Déversoir de l'isle-Maligne-2	Water	Active	

QC Power - Isle-Maligne	Déversoir de l'Isle-Maligne-5A	Water	Active	
QC Power - Isle-Maligne	Digue de l'Isle-Maligne-5B	Water	Active	
QC Power - Isle-Maligne	Digue de l'Isle-Maligne-6	Water	Active	
QC Power - Isle-Maligne	Digue de l'Isle-Maligne-8	Water	Active	
QC Power - Isle-Maligne	Évacuateur de l'Isle-Maligne-3	Water	Active	
QC Power - Isle-Maligne	Évacuateur de l'Isle-Maligne-4	Water	Active	
QC Power - Isle-Maligne	Évacuateur de l'Isle-Maligne-5	Water	Active	
QC Power - Isle-Maligne	Évacuateur de l'Isle-Maligne-7	Water	Active	
QC Power - Manouane	Barrage de Manouane	Water	Active	
QC Power - Manouane	Digue Bellevue-1A	Water	Active	
QC Power - Manouane	Digue Bellevue-1B	Water	Active	
QC Power - Manouane	Digue Bonnard	Water	Active	
QC Power - Manouane	Digue de Manouane-4	Water	Active	
QC Power - Manouane	Digue de Manouane-4A	Water	Active	
QC Power - Manouane	Digue de Manouane-4B	Water	Active	
QC Power - Manouane	Digue de Manouane-4C	Water	Active	
QC Power - Manouane	Évacuateur Bonnard	Water	Active	
QC Power - Passes-Dangereuses, Quebec, Canada	Barrage des Passes-Dangereuses	Water	Active	
QC Power - Passes-Dangereuses, Quebec, Canada	Digue des Passes-Dangereuses-2	Water	Active	
QC Power - Passes-Dangereuses, Quebec, Canada	Digue des Passes-Dangereuses-3	Water	Active	
QC Power - Passes-Dangereuses, Quebec, Canada	Digue des Passes-Dangereuses-4	Water	Active	
QC Power - Shipshaw, Quebec, Canada	Barrage de Shipshaw	Water	Active	
QC Power - Shipshaw, Quebec, Canada	Barrage de Shipshaw-2	Water	Active	
QC Power - Shipshaw, Quebec, Canada	Barrage de Shipshaw-3A	Water	Active	
QC Power - Shipshaw, Quebec, Canada	Barrage de Shipshaw-3B	Water	Active	
QC Power - Shipshaw, Quebec, Canada	Barrage de Shipshaw-4A	Water	Active	
QC Power - Shipshaw, Quebec, Canada	Barrage de Shipshaw-5	Water	Active	
QIT Madagascar Minerals (QMM), Madagascar	Feed Prep Tails	Tailings	Active	No embankment - excavated storage facility

QIT Madagascar Minerals (QMM), Madagascar	Lakefront Wetland	Water	Active	
QIT Madagascar Minerals (QMM), Madagascar	Paddock Ponds	Water	Active	
QIT Madagascar Minerals (QMM), Madagascar	Settling Pond	Tailings	Active	No embankment - excavated storage facility
Queensland Alumina Ltd (QAL), QLD, Australia	Ash Pond 1	Tailings	Closed	Centreline
Queensland Alumina Ltd (QAL), QLD, Australia	Ash Pond 2	Tailings	Closed	Centreline
Queensland Alumina Ltd (QAL), QLD, Australia	Ash Pond 3	Tailings	Closed	Centreline
Queensland Alumina Ltd (QAL), QLD, Australia	Ash Pond 4	Tailings	Active	Centreline
Queensland Alumina Ltd (QAL), QLD, Australia	East Contaminants Pond	Tailings	Active	Downstream
Queensland Alumina Ltd (QAL), QLD, Australia	Mineral Waste Disposal Facility	Tailings	Active	Upstream
Queensland Alumina Ltd (QAL), QLD, Australia	Neutralising Pond	Tailings	Active	Downstream
Queensland Alumina Ltd (QAL), QLD, Australia	Red Mud Dam 1	Tailings	Active	Upstream
Queensland Alumina Ltd (QAL), QLD, Australia	Red Mud Dam 2	Tailings	Active	Upstream
Queensland Alumina Ltd (QAL), QLD, Australia	South Trees Water Mangement Ponds	Water	Active	
Queensland Alumina Ltd (QAL), QLD, Australia	West Coal Stilling Pond	Water	Active	
Queensland Alumina Ltd (QAL), QLD, Australia	West Contaminants Pond	Tailings	Active	Downstream
Resolution, Arizona, USA	No. 1 and 2 TSF Impoundment	Tailings	Post closure	Upstream
Resolution, Arizona, USA	No. 3 and 4 TSF Impoundment	Tailings	Post closure	Upstream
Resolution, Arizona, USA	No. 5 TSF Impoundment	Tailings	Under rehabilitation	Upstream
Resolution, Arizona, USA	No. 6 and 7 TSF Impoundment	Tailings	Under rehabilitation	Upstream, Centreline
Resolution, Arizona, USA	SSI North and South ponds WSF	Water	Active	
Richards Bay Minerals (RBM), South Africa	Clarifier Sludge Pond Phase II	Tailings	Active	Downstream

Richards Bay Minerals (RBM), South Africa	Nhlabane Lake	Water	Active	
Ridgeway, South Carolina, USA	Bear Creek Pond	Water	Active	
Ridgeway, South Carolina, USA	Process Solution Pond	Water	Active	
Ridgeway, South Carolina, USA	Ridgeway TSF	Tailings	Closed	Downstream
Robe Valley, WA, Australia	TSF1	Tailings	Under rehabilitation	No embankment - excavated storage facility
Robe Valley, WA, Australia	TSF2	Tailings	Closed	Downstream
Robe Valley, WA, Australia	TSF2.5	Tailings	Closed	No embankment - excavated storage facility
Robe Valley, WA, Australia	TSF3 North	Tailings	Inactive	Downstream
Robe Valley, WA, Australia	TSF3 South	Tailings	Closed	Downstream
Robe Valley, WA, Australia	TSF4	Tailings	Active	Upstream
Robe Valley, WA, Australia	TSF5	Tailings	Active	Downstream
Robe Valley, WA, Australia	TSF6 - Project	Tailings	Active	No embankment - excavated storage facility
Robe Valley, WA, Australia	TSF7 - Project	Tailings	Under construction	No embankment - excavated storage facility
Rössing, Namibia	Seepage Dam	Water	Active	
Rössing, Namibia	Tailings Storage Facility (TSF)	Tailings	Active	Upstream
Saint Cyr, Marseille, France	Saint Cyr 0426	Tailings	Post closure	Upstream
Salindres, France	Salindres 0431 - B2	Tailings	Under rehabilitation	Upstream
Segoussac, Rousson, France	Segoussac 0126	Tailings	Post closure	Upstream, Downstream
Sept-Iles, Quebec, Canada	Sainte-Marguerite Dam	Water	Active	
Sorel-Tracy, Quebec, Canada	P84 Polishing Pond	Water	Active	
Sorel-Tracy, Quebec, Canada	P84 Tailings	Tailings	Active	No embankment - dry stack
Sweetwater, Wyoming, USA	Kennecott Uranium	Tailings	Inactive	Single embankment
Tom Price, WA, Australia	TSF1	Tailings	Inactive	Downstream
Tom Price, WA, Australia	TSF2A	Tailings	Active	Upstream
Vaudreuil (Complexe Jonquière), Quebec, Canada	Laterriere RDA - Basins XC-XD	Tailings	Inactive	Centreline
Vaudreuil (Complexe Jonquière), Quebec, Canada	Local Ponds RDA (Local RDA) - Jonquiere Site	Tailings	Active	Upstream, Centreline, Downstream
Vaudreuil (Complexe Jonquière), Quebec, Canada	Pond 4	Water	Active	

Weipa & Amrun, QLD, Australia	Andoom TSF	Tailings	Active	Upstream
Weipa & Amrun, QLD, Australia	Arraw WSF	Water	Active	
Weipa & Amrun, QLD, Australia	East Weipa Emergency TSF	Tailings	Active	Downstream
Weipa & Amrun, QLD, Australia	East Weipa TSF1 and 2 (EW1 & 2)	Tailings	Inactive	Downstream
Weipa & Amrun, QLD, Australia	East Weipa TSF4 (EW4)	Tailings	Active	Upstream
Weipa & Amrun, QLD, Australia	Ely Dam WSF	Water	Active	
Weipa & Amrun, QLD, Australia	G & X Dam	Tailings	Under rehabilitation	Upstream
Weipa & Amrun, QLD, Australia	G2 Dam	Tailings	Inactive	Downstream
Weipa & Amrun, QLD, Australia	Torro TSF	Tailings	Active	Upstream
Weipa & Amrun, QLD, Australia	West Weipa TSF2 Dam (including G1 Dam)	Tailings	Inactive	Upstream
Whinnyhall, Scotland	Kinghorn Loch	Water	Inactive	
Whinnyhall, Scotland	Whinnyhall Landfill	Tailings	Inactive	Centreline
Yandicoogina, WA, Australia	WFC1	Tailings	Inactive	Downstream
Yandicoogina, WA, Australia	WFC2/4	Tailings	Active	Centreline
Yandicoogina, WA, Australia	WFC3	Tailings	Inactive	Downstream
Yandicoogina, WA, Australia	WFC3A	Tailings	Active	Downstream
Yarwun, QLD, Australia	Eastern first flush	Water	Active	
Yarwun, QLD, Australia	Northern laydown area sedimentation pond	Water	Active	
Yarwun, QLD, Australia	Residue Management Area 1 (RMA1)	Tailings	Active	Downstream
Yarwun, QLD, Australia	Southern laydown area sedimentation pond	Water	Active	
Yarwun, QLD, Australia	West Construction water	Water	Active	

**Not owned and not operated by Rio Tinto. However, as a result of the exercise of a call option on the real property, ownership of the facilities may revert back to Rio Tinto.*